



SANTA FE MAC REPAIR

SANTAFEMACREPAIR.COM • LIGHTIMAGINATION.NET

505-652-7701 • in@sfmacrepair.com
133 Del Rio dr., SANTA FE, NM 87501

BATTERY CALIBRATION

This process is a good for old batteries with weak charge or service battery flag. Especially if this was never done before. Can be performed even 2-3 times in sequence for best results (this is not guaranteed, most old batteries will need to be replaced).

Process allows to flush and re-establish the empty and full battery levels.

If battery is swollen or has other signs of malfunction, disconnect (if possible) and get it replaced.

* Recycle old battery, it's not a trash.

- 1) let your battery fully charge 6-8h, use it with a power adapter plugged in for the whole time of use.
- 2) fully discharge the battery, by running on battery only, when close to low battery, restart the computer with OPTION key pressed - laptop will go into boot options, let it sit and drain battery until shutdown. Let it sit few minutes and try to turn it on, if it does, repeat the process until the battery is completely empty and won't turn on. Optionally, press "T" key if laptop has firewire/thunderbolt rather than option key - it will go into target disc mode.
- 3) let it rest overnight (8h) in that fully discharged state
- 4) in the morning, let it fully charge for 6-8h, use it only on power adapter during that time. do SMC reset during or before the charging process http://support.apple.com/kb/HT3964?viewlocale=en_US&locale=en_US
- 5) resume normal operation and check battery status.

TECHNOLOGY / MULTIMEDIA / PHOTOGRAPHY

